



INPUT MODE	JPx	INx.1	INx.2
S300	A+F+G	+	-
THERMISTOR	B+D+G	GND	INPUT
Pt1000	C+D+G	GND	INPUT
0-10V	D+E	GND	INPUT
0-20mA	D+G+H	GND	INPUT
PULSE CNT	B+D+G	GND	INPUT
BINARY	B+D+G	GND	INPUT
SWITCH	B+D+G	GND	INPUT